## Gear / ATF

## **BIZOL PRESS RELEASE**



a burning smell 05/05/2022

A smell of burning can appear as a result of a low level or contamination of the transmission gear fluid, indicating a possible leak of the transmission gear oil or the need for it to be changed.

## **BIZOL Gear Oil**

**ATTENTION!** Follow the instructions of car manufacturer!

Firstly, we would advise you to diagnose the manual gear box and clutch by specialists.

## BIZOL transmission gear oils will allow you to avoid problems and premature wear and tear and will also provide:

- · smooth gear shifting
- elimination of vibration
- · reduced wear and tear
- reduced friction
- · heat transfer from rubbing surfaces
- protection against corrosion