

a burning smell

05/05/2022

A smell of burning can appear as a result of a low level or contamination of the transmission gear fluid, indicating a possible leak of the transmission gear oil or the need for it to be changed.

BIZOL Gear Oil

ATTENTION! Follow the instructions of car manufacturer!

Firstly, we would advise you to diagnose the manual gear box and clutch by specialists.

BIZOL transmission gear oils will allow you to avoid problems and premature wear and tear and will also provide:

- smooth gear shifting
- elimination of vibration
- reduced wear and tear
- reduced friction
- heat transfer from rubbing surfaces
- protection against corrosion